

**CONTROL ISSUES - SHOULD BE ADDRESSED
THROUGH PDMT C&I FIRST**

ASP CODE	OPPORTUNITY	SIT C&I # IF APPLICABLE	SIT PRIORITY RANK (SEPT 1999)
Y	Reduction in % OOC for prep parameters.	49	62.5
KK	Decrease area process control performance (Machine Room Lines I & III).	52	62
JJ	Decrease Run Pulper Solubles OOC's.	51	57.5